



NOTE: Discharge outlet shall never be below crown of downstream pipe.

DETAIL NO.
G-3442

CITY OF GOODYEAR
STANDARD DETAIL

APPROVED BY:
Goodyear Standards and
Policies Committee 7/97

FORCE MAIN - MANHOLE DISCHARGE

DETAIL NO.
G-3442